



JON M. HUNTSMAN, JR.  
Governor  
GARY R. HERBERT  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report

#### Minerals Regulatory Program

Date: October 21, 2008

Reviewed: 

<b>Mine Name:</b> Worthington Landscape	<b>Permit Number:</b> S/035/0025
<b>Operator Name:</b> Worthington Landscape	<b>Inspection Date:</b> 10/16/2008
<b>Inspector(s):</b> Brett Gregory for Leslie Heppler	<b>Time:</b> 10:00 am
<b>Other Participants:</b> None	<b>Mine Status:</b> Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**Bond Amount:** \$5,000

**Permit fee:** Delinquent for 2007 & 2008

**Purpose of Inspection:** This was a routine annual inspection of the site.

**Inspection Summary:** Photos attached.

1) The permit fee is delinquent for 2007 & 2008, at the time the inspection report was written. The bond amount is inadequate for the amount of disturbance found.

6) Concurrent reclamation is recommended for ongoing mining.

**Conclusions and Recommendations:** Pay all annual fees that are due. Operator needs to reclaim areas or increase the bond amount. DOGM will continue to monitor this site.

**Inspector's Signature**

BG:vs

cc: Craig Worthington

O:\M035-SaltLake\0350025-Worthington\inspections\insp-10162008.doc



Machinery found on site



Disturbed area -Another view looking north



Disturbed area



Disturbed area - facing west



Another extent of disturbance



Road entrance to site – Disturbed area.



Road through site - Disturbed area.



Disturbed area